

HAINES AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

- Location: Haines Airport is located just north of the City of Haines in the northern part of Southeast Alaska.
- District: Southeast
- Airport Manager: Pete Lapham
- District Maintenance Manager: Gary Hayden
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction:
 - 1992
- Pavement layout:
 - It has Runway 8-26 that is 3600' x 100', a full parallel Taxiway, four cross Taxiways (A – D), a Main Apron and a Helipad.
- Design Aircraft: Twin Otter
- 2001 Enplanements: 9,652
- Airport Class: Non-Primary
- Last pavement condition survey: May 13, 2003
- Next planned pavement condition survey: 2006
- 2003 reported pavement maintenance and/or changed conditions:
 - No reports

Recommendations:

- Crack seal and patch as needed